



◆ MARKING AND DATE CODE

Trade Mark "CS"	Chinsan Solid Capacitor, Show on Dimension $\geq 8\phi$																																																		
Code (Date Code)	<p>(1)DAY</p> <table border="1" style="width: 100%; text-align: center;"> <tr><th>Code</th><th>1</th><th>2</th><th>3</th></tr> <tr><td>Day</td><td>1st~10th</td><td>11~20th</td><td>21st~31st</td></tr> </table> <p>(2)Month</p> <table border="1" style="width: 100%; text-align: center;"> <tr><th>Code</th><th>1</th><th>2</th><th>3</th><th>4</th><th>5</th><th>6</th></tr> <tr><td>Month</td><td>Jan</td><td>Feb</td><td>Mar</td><td>Apr</td><td>May</td><td>Jun</td></tr> <tr><th>Code</th><th>7</th><th>8</th><th>9</th><th>X</th><th>Y</th><th>Z</th></tr> <tr><td>Month</td><td>July</td><td>Aug</td><td>Sep</td><td>Oct</td><td>Nov</td><td>Dec</td></tr> </table> <p>(3)Year</p> <table border="1" style="width: 100%; text-align: center;"> <tr><th>Code</th><th>6</th><th>7</th><th>8</th><th>9</th><th>0</th><th>1</th></tr> <tr><td>Year</td><td>2016</td><td>2017</td><td>2018</td><td>2019</td><td>2020</td><td>2021</td></tr> </table>	Code	1	2	3	Day	1st~10th	11~20th	21st~31st	Code	1	2	3	4	5	6	Month	Jan	Feb	Mar	Apr	May	Jun	Code	7	8	9	X	Y	Z	Month	July	Aug	Sep	Oct	Nov	Dec	Code	6	7	8	9	0	1	Year	2016	2017	2018	2019	2020	2021
Code	1	2	3																																																
Day	1st~10th	11~20th	21st~31st																																																
Code	1	2	3	4	5	6																																													
Month	Jan	Feb	Mar	Apr	May	Jun																																													
Code	7	8	9	X	Y	Z																																													
Month	July	Aug	Sep	Oct	Nov	Dec																																													
Code	6	7	8	9	0	1																																													
Year	2016	2017	2018	2019	2020	2021																																													
Series (Print Code)	<table border="1" style="width: 100%; text-align: center;"> <tr> <th>Series</th><th>UPS</th><th>UPR</th><th>UL</th><th>UPE</th><th>RP</th><th>RH</th><th>GP</th><th>GV</th><th>GS</th><th>SG</th><th>SP</th><th>SU</th><th>SE</th> </tr> <tr> <td><math>\phi 5 \sim \phi 6.3</math></td><td>--</td><td>R</td><td>L</td><td>E</td><td>--</td><td>H</td><td>P</td><td>V</td><td>--</td><td>G</td><td>P</td><td>U</td><td>E</td> </tr> <tr> <td><math>\phi 8 \sim \phi 10</math></td><td>UPS</td><td>--</td><td>UL</td><td>UPE</td><td>RP</td><td>RH</td><td>GP</td><td>GV</td><td>GS</td><td>SG</td><td>SP</td><td>SU</td><td>SE</td> </tr> </table>	Series	UPS	UPR	UL	UPE	RP	RH	GP	GV	GS	SG	SP	SU	SE	$\phi 5 \sim \phi 6.3$	--	R	L	E	--	H	P	V	--	G	P	U	E	$\phi 8 \sim \phi 10$	UPS	--	UL	UPE	RP	RH	GP	GV	GS	SG	SP	SU	SE								
Series	UPS	UPR	UL	UPE	RP	RH	GP	GV	GS	SG	SP	SU	SE																																						
$\phi 5 \sim \phi 6.3$	--	R	L	E	--	H	P	V	--	G	P	U	E																																						
$\phi 8 \sim \phi 10$	UPS	--	UL	UPE	RP	RH	GP	GV	GS	SG	SP	SU	SE																																						

◆ LEAD FORMING TYPE

Type	Part Number	Dimensions (Unit: mm)															
		$\phi D$	F	t	L (Part number for lead length and pitch for taping)												
					3	4	U	7	D	X	R	B	E	G	2	M	T
					3.5	4.5	5.5	7	4	2.3	2.5	2.8	3.1	3.3	2.5	3.5	3.8
					$\pm 0.5$					$\pm 0.2$			$\pm 0.3$				
Cut	C	5	2	----													
		6.3	2.5	----													
		8	3.5	----													
		10	5	----													

◆ TAPING

Figure 1	Symbol	Tolerance	Φ 5		Φ 6.3		Φ 8	
			PS	P5	PS	P5	PS	P5
	Φd	±0.05	0.45		0.45/0.6		0.6	
	P	±0.1	12.7		12.7		12.7	
	P0	±0.2	12.7		12.7		12.7	
	P1	±0.5	3.85		3.85		3.85	
	P2	±1.0	6.35		6.35		6.35	
	F	+0.8	5		5		5	
		-0.2						
	H	±0.5	17.5	18.5	17.5	18.5	17.5	18.5
	H0	±0.5	16		16		16	
	W	±0.5	18		18		18	
	W0	Minimum	12.5		12.5		12.5	
	D0	±0.2	4		4		4	
	t	±0.2	0.7		0.7		0.7	

Figure 2	Symbol	Tolerance	Φ 6.3	Φ 8			Φ 10
			P2	P3	H3	P7	P5
	Φd	±0.05	0.45/0.6	0.6			0.6
	P	±0.1	12.7	12.7			12.7
	P0	±0.2	12.7	12.7			12.7
	P1	±0.5	5.6	4.6			4.6
	P2	±1.0	6.35	6.35			6.35
	F	+0.8	2.5	3.5			5
		-0.2					
	H	±0.5	18.5	18.5	20	17.5	18.5
	H0	±0.5	-	-			-
	W	±0.5	18	18			18
	W0	Minimum	12.5	12.5			12.5
	D0	±0.2	4	4			4
	t	±0.2	0.7	0.7			0.7

Figure 3	Symbol	Tolerance	Φ 5
			PZ
	Φd	±0.05	0.45
	P	±0.1	12.7
	P0	±0.2	12.7
	P1	±0.5	5.6
	P2	±1.0	6.35
	F	+0.8	2.0
		-0.2	
	H	±0.5	18.5
	H0	±0.5	-
	W	±0.5	18
	W0	Minimum	12.5
	D0	±0.2	4
	t	±0.2	0.7